

<http://www.pocket-lint.com/news/5646/sony-defect-cyber-shot-digital-cameras>

Sony finds defect in Cyber-shot digital cameras

Eight models affected

by Stuart Miles published on 24 November 2006

First it was the company's laptop batteries that ended in recalling almost 10 million units, now it looks like Sony has been hit with a dodgy batch digital cameras.

Sony has announced that its Cyber-shot compact digital cameras might not work in warm and humid areas and that it would repair any affected cameras free of charge.

The cameras affected are DSC-F88, DSC-M1, DSC-T1, DSC-T11, DSC-T3, DSC-T33, DSC-U40 and DSC-U50 models.

In a statement from Sony, the LCDs in the eight models above may not show images correctly or the cameras may not be able to take photos at all.

Out of the 1 million cameras sold between September 2003 to January 2005, Sony expects just 4000 could need repairs.

