

<http://www.pocket-lint.com/news/18657/macbooks-shipped-two-ms-faults>

## Some MacBooks shipped with two "m" keys

Does that make it a MacMook?

by Amy-Mae Elliott published on 23 October 2008

It appears Apple may have a few quality control issues with the new MacBooks. Reports are coming in that see the shiny new machines shipping with two "m" keys ("b" was over-rated anyway), loose battery covers and slanted function keys.

